


NO. 48207-330 SHT.

NO. 48207-330 SHT.



NOTES:

QUALITY ASSURANCE (RECEIVING INSPECTION)

1. COMPRESS GASKET AT JOINT AREA DOWN TO .13". JOINTS MUST NOT SEPARATE.
2. PULL TEST: PULL GASKET ACROSS CORNERS UNTIL TEAR IS NOTED. GASKET MUST NOT TEAR AT BOND.

VENDOR:
BUCKLEY INDUSTRIES

⊙⊙
ZOTEFOM MP-33, PALZIV POL. APV2.8-03 OR OLETEX BKJN-300
CROSS-LINKED POLYETHYLENE FOAM WITH FILM OR SCRIM
SUPPORTED ACRYLIC ADHESIVE BACKING & RELEASE LINER

NO. 8322a330	UNLESS OTHERWISE SPECIFIED	MATERIAL
TOLERANCES DECIMAL	◇ DIM. TO TANGENT POINT	FINISH SPEC.
XXX .1	◇ DIM. TO INSIDE MOLD LINE	NAME
XX .03	◇ DIM. TO OUTSIDE MOLD LINE	BASEPAN GASKET
X .005	◇ BEND RADIUS	NO. 48207-330
ANGULAR ± 1°	◇ PROJECTION - ALL DIMENSIONS IN INCHES - DO NOT SCALE PRINT	
FRACTIONAL ± 1/32		

ECO		REVISIONS	
BY	DATE	DESCRIPTION	DATE
A	06/27/11	FOR LOCO MACH. UNIT	
B	06/29/16	AL. ADDED MATERIAL: PALZIV POL. APV2.8-03	

RV PRODUCTS	REVISION
AIRKCEL INCORPORATED	OF
WICHITA, KANSAS	CHECKED
SCALE	DATE
NONE	06-23-11
APPROVED	P. R.